



202-293-7060

Fig. 3A





MURAKAMI et al Q64831
BATTERY TERMINAL AND BATTERY POST
ADAPTOR

Filed: June 5, 2001 Darryl Mexic 4 of 16

202-293-7060

Fig. 4







Fig. 5








6 of 16

Fig. 8A





Filed: June 5, 20 Darryl Mexic 7 of 16

202-293-7060

Fig. 9A





Fig. 9B



202-293-7060

8 of 16

Fig. 10A






Fig. 10B



MURAKAMI et al Q64831
BATTERY TERMINAL AND BATTERY POST
ADAPTOR
Filed: June 5, 2001
Darryl Mexic 202-293-7060
9 of 16


Fig. 11




MURAKAMI et al Q64831
BATTERY TERMINAL AND BATTERY POST
ADAPTOR
Filed: June 5, 2001
Darryl Mexic 202-293-70
10 of 16 202-293-70

202-293-7060







Darryl Mexic 11 of 16

202-293-7060

Fig. 14





Fig. 15



Filed: June 5, 200 Darryl Mexic 12 of 16

202-293-7060

Fig. 16





Fig. 17



ADAPTOR
Filed: June 5, 2001
Darryl Mexic
13 of 16

202-293-7060

Fig. 18





Fig. 19



Filed: June 5, 2001 Darryl Mexic 14 of 16

202-293-7060

Fig. 20A






Fig. 20B



MURAKAMI et al Q64831
BATTERY TERMINAL AND BATTERY POST
ADAPTOR
Filed: June 5, 2001
Darryl Mexic 202-293-7060
15 of 16

Fig. 21



Filed: June 5, 2001 Darryl Mexic

16 of 16

202-293-7060

Fig. 22




Fig. 23




Fig. 24

